

WELL COMPLETION REPORT
3/71

LAKE CARMEL
41 27 56 73 40 12

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P1077

OWNER	NAME Jack Smith		ADDRESS Quaker Rd	
LOCATION OF WELL	(No. & Street) Quaker Rd.		(Town) Lake Carmel	(Lot Number) N.Y.
PROPOSED USE OF WELL	<input checked="" type="checkbox"/> DOMESTIC <input type="checkbox"/> BUSINESS ESTABLISHMENT <input type="checkbox"/> FARM <input type="checkbox"/> TEST WELL <input type="checkbox"/> PUBLIC SUPPLY <input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> AIR CONDITIONING <input type="checkbox"/> OTHER (Specify) 700 S			
DRILLING EQUIPMENT	<input type="checkbox"/> ROTARY <input checked="" type="checkbox"/> COMPRESSED AIR PERCUSSION <input type="checkbox"/> CABLE PERCUSSION <input type="checkbox"/> OTHER (Specify)			
CASING DETAILS	LENGTH (feet) 20'	DIAMETER (inches) 7"	WEIGHT PER FOOT 26	<input checked="" type="checkbox"/> THREADED <input type="checkbox"/> WELDED DRIVE SHOE <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO WAS CASING GROUTED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
YIELD TEST	<input type="checkbox"/> BAILED <input type="checkbox"/> PUMPED <input checked="" type="checkbox"/> COMPRESSED AIR		HOURS 2	G.P.M. 2 YIELD (G.P.M.) 2
WATER LEVEL	MEASURE FROM LAND SURFACE - STATIC (Specify feet) 30		DURING YIELD TEST (feet) total drawdown	
SCREEN DETAILS	MAKE			LENGTH OPEN TO AQUIFER (feet)
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches): GRAVEL SIZE (inches) FROM (feet) TO (feet)
DEPTH FROM LAND SURFACE FEET to FEET		FORMATION DESCRIPTION		Sketch exact location of well with distances, to at least two permanent landmarks:
0 5		overburden		
5350		gray granite		
If yield was tested at different depths during drilling, list below				
FEET		GALLONS PER MINUTE		
DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)		BOYD ARTESIAN WELL C
9/14/72	10/14/72			RD 3 ROUTE 53 CARMEL, N.Y.